

Information BULLETIN

Issue No: MG016B Date: 18th February 2017

Products Affected:

- i McMurdo SmartFind EPIRB – All Versions
- i Kannad Marine EPIRB, Sport/Sport Pro/Sport Pro +

Top dome replacement


Dear Partner,

It has come to our attention that the top dome under certain circumstances may begin to show signs of localised craze cracking. Small cracks may appear to be radiating out from the three over moulded screw inserts.



Important:-

The cracking area is outside of the waterproof seal (main O ring seal) in a wet zone which is a self-draining cavity. As such, any cracking in this area will not compromise the waterproof body seal in anyway, or significantly weaken the overall integrity of the EPIRB.



Recommendation:

1. Clearly, any cracking is undesirable and unsightly and our recommendation is that the EPIRB should be subject to rectification work at earliest opportunity.
2. Should you have any concern with regarding the condition of your EPIRB you are invited in the first instance to contact the McMurdo customer support team for advice.
3. If the EPIRB is in warranty period, complete an RMA application using the online form:-

<http://www.mcmurdogroup.com/contact/support/marine-products/>

Issue 01/02.17

McMurdo believes that if you have any doubts about the condition of any safety apparatus, you should have it reviewed by an expert before it is deployed as your primary search and rescue equipment.

Although the dome cracking is superficial and won't impact on operational effectiveness of the beacon, customer safety and confidence in McMurdo's products is our primary concern. If you need further information regarding the issue or rectification process, please contact our customer service team for further advice.

Contact Information:

Email: service.uk@mcmurdogroup.com

Phone: +44 (0)2392 623900

Author	Paul Adams
Authorised	Robin George
Date	15.02.2017

To be carried out immediately	<input type="checkbox"/>
To be carried out during normal service	<input type="checkbox"/>
To be carried out if required	<input type="checkbox"/>
To be carried out only on PCB repair	<input type="checkbox"/>
For information only	<input checked="" type="checkbox"/>